

Weekly Progress Report



Executive Summary

ON-SITE ACTIVITY UPDATE



WEEK ENDING 05/22/20:

- Crushing and embanking activities ongoing
- North and South Sloping continued
- Oval Green fill work complete
- Multi-Modal Sidewalk rock ongoing
- Multi-Modal pathways and seat wall beginning
- Parking lot cover soil work ongoing

WEEK ENDING 05/29/20:

- Crushing activities ongoing
- Embanking and sloping the south side of the pit ongoing
- Multi-Modal Sidewalk rock ongoing
- Multi-Modal pathways and seat wall beginning
- Parking lot cover soil work complete

FORTIS CONSTRUCTION CONTACT INFORMATION:

Barry Shephard
 C: 503-730-3427
 Barry.Shephard@fortisconstruction.com
 Future Parking lot grading



PHOTOS

Crushing activities, South slope benching, embanking, and sloping



Oval Green Top soil



NW slope of pit