

# Weekly Progress Report



## Executive Summary

### ON-SITE ACTIVITY UPDATE



#### WEEK ENDING 06/05/20:

- Crushing activities ongoing
- Embanking and sloping the south side of the pit ongoing
- Multi-Modal Sidewalk rock complete
- Multi-Modal pathways and seat wall ongoing
- Fencing beginning

#### WEEK ENDING 06/12/20:

- Crushing activities ongoing
- Embanking and sloping the south side of the pit ongoing
- Multi-Modal Seat Wall ongoing with stone placement
- Multi-Modal pathways and seat wall ongoing
- Fencing ongoing, including split-rail fence

#### FORTIS CONSTRUCTION CONTACT INFORMATION:

Barry Shephard  
 C: 503-730-3427  
 Barry.Shephard@fortisconstruction.com



### PHOTOS

South side of the pit embanking, sloping, crushing activities, and oval green



Northwest side of pit sloping



Future Parking Lot