

Weekly Progress Report



Executive Summary

ON-SITE ACTIVITY UPDATE



WEEK ENDING 06/12/20:

- Crushing activities ongoing
- Embanking and sloping the south side of the pit ongoing
- Multi-Modal Seat Wall ongoing with stone placement
- Fencing ongoing, including split-rail fence

WEEK ENDING 06/19/20:

- Crushing activities ongoing
- Embanking and sloping the south side of the pit ongoing
- Split Rail and other fencing ongoing
- North Access Road beginning
- Hydroseeding

FORTIS CONSTRUCTION CONTACT INFORMATION:

Barry Shephard
 C: 503-730-3427
 Barry.Shephard@fortisconstruction.com

Seat Wall at future Overlook area



PHOTOS

View of the pit from the west cliff wall – crushing, split rail fence, and embanking activities on the south side of the pit



Northwest side of pit sloping



South side of pit embanking and sloping