

Weekly Progress Report



Executive Summary

ON-SITE ACTIVITY UPDATE



WEEK ENDING 06/19/20:

- Crushing activities ongoing
- Embanking and sloping the south side of the pit ongoing
- Split Rail and other fencing ongoing
- North Access Road beginning

WEEK ENDING 06/26/20:

- Crushing activities ongoing
- Embanking and sloping the south side of the pit compete
- North Access Road, Roundabout, and Nub work ongoing
- Hydroseeding beginning
- Site fence work ongoing

FORTIS CONSTRUCTION CONTACT INFORMATION:

Barry Shephard
 C: 503-730-3427
 Barry.Shephard@fortisconstruction.com

Split Rail fence at west side of pumice mine



PHOTOS

View of the pit looking north – material processing and north slope



Overlook area and seat wall on the south side of the pumice mine



South pit embanking and sloping

Walkways at overlook area

