

Weekly Progress Report



Executive Summary

ON-SITE ACTIVITY UPDATE



WEEK ENDING 06/26/20:

- Crushing activities ongoing
- Embanking and sloping the south side of the pit compete
- North Access Road, Roundabout, and Nub work ongoing
- Hydroseeding beginning
- Site fence work ongoing

WEEK ENDING 07/03/20:

- Demobilization of crusher
- North Access Road and roundabout grading complete
- Hydroseeding complete
- Site fence work ongoing
- Overlook walkways complete

FORTIS CONSTRUCTION CONTACT INFORMATION:

Kat Stevens
 C: 510-593-8818
 Kat.Stevens@fortisconstruction.com

Overlook area seat wall



PHOTOS

View of the pit looking east – slopes being hydroseeded, oval green complete, and crusher demobilizing



South slope completion



Overlook area walking paths with woodchips